

WELL INSPECTION REPORT

License #'s (ALCORH824KJ) (ALCORPF825RP) (ALCORPF8259P)

ROC # 339937

GENERAL INFORMATION

CUSTOMER NAME:

PROPERTY ADDRESS:



INSPECTION DATE:

11/15/2023

INSPECTOR NAME:

Craig Benfit and Josh Inman



Water Source Information

SOURCE: HAND DUG □ DRILLED ☒ RIVER/LAKE □ UNKNOWN □ OTHER □ WELL LOG: YES □ NO ☒ WELL DEPTH: Unknown WELL LOCATION: Outside ☒ Inside Pump House □ Vault/Underground ☒ UNKNOWN □ OTHER □								
GOOD ACCESS TO WELL HEAD: YES 🗵 NO 🗆								
CASING TYPE & DIAMETER: 7" Steel								
DISTANCE FROM POTENTIAL POLLUTION SOURCES:100 +								
WELL HEAD CONDITIONS: SIZE: _7" CAP ⊠ SANITARY SEAL□ VENTED? YES ⊠ NO □ VERMIN PROOF? YES ⊠ NO □ NEEDS REPLACMENT? YES □ NO ⊠								
NOTES: N/A								
Well Pump Equipment								
PUMPS: 1 🛛 Submersible 2 🗆 3 🗆 4 🗆								
BRAND/MODEL: Submersible in well – Unknown Brand LOCATION OF PUMP/'S: In well HP/'s: 1.5HP VOLTAGE: _230 VAC								
WIRE SIZE: MAX AMP:								
WIRE SIZE: #8 MAX AMP: 11.2								
WIRE SIZE:#8 MAX AMP:11.2 RUNNING AMPERAGE:10.2 PUMPING RATE:5 GPM on a 1HR Flow test								
WIRE SIZE:#8 MAX AMP:11.2 RUNNING AMPERAGE: 10.2 PUMPING RATE:5 GPM on a 1HR Flow test PUMP'S RUNNING DURATION FROM CUT IN TO CUT OUT: 8 Min 45 Sec.								

This Report is not to be used to determine compliance with any regulations, laws, or rules. Its sole purpose is to attempt to evaluate the operating performance of the well and pump(s) at the time of inspection. Anything can change at a moment's notice.













CONTROL SYSTEM AND OTHER INFORMATION

CONTROL SYSTEM/'S:							
CONTROL BOX: YES ⊠ NO ☐ QUANTITY: 1							
BRAND: Franklin Electric HP: 1.5 Deluxe W/Mag Contactor							
CONDITION: GOOD ☐ OPERABLE ☑ NEEDS REPLACEMENT ☑							
PRESSURE SWITCH: Sq D RANGE: 40-60 SENSOR: N/A							
OHMS VALUES: RY: 9.2 BY: 3.2 RB: 11.0 GROUNDING? YES □ NO ☒							
NOTES: The starting capacitor is leaking in the control box, and we recommend replacing before it							
fails or causes the well pump to fail.							
WIRING AND PLUMBING:							
WIRING FROM C/B TO TOP OF WELL HEAD IS? #8 in Conduit							
WIRING FROM TOP OF WELL HEAD DOWN TO MOTOR? Unable to remove well cap because of rusted bolts							
IS WIRING UP TO CODE IN PUMP HOUSE? YES □ NO ☒ No pump house							
CONDITION OF WIRING: GOOD ☐ OPERABLE ☑ NEEDS REPLACEMENT ☐							
IS WIRING IN CONDUIT? YES □ NO ☒ IS WIRING SAFE? YES ☒ NO □							
IS PLUMBING UP TO CODE? YES □ NO ☒							
CONDITION OF PLUMBING: GOOD ☐ OPERABLE ☑ NEEDS REPLACEMENT ☐							
NOTES: _The electrical wiring from the pressure switch to the control box is not in conduit and stapled to							
the railing outside where rodents can chew on it.							

This Report is not to be used to determine compliance with any regulations, laws, or rules. Its sole purpose is to attempt to evaluate the operating performance of the well and pump(s) at the time of inspection. Anything can change at a moment's notice.













CONTROL SYSTEM AND OTHER INFORMATION

PRESSURE TANK/'S:

YES 🛚	NO [] NUM	IBER OF TANKS	: 1	\boxtimes	2 🗆	3 🗆	4 🗆	5 🗆	
MAKE:	Prolin	e by Am	trol	TYPE	Ble	adder			LOCATION:	Laundry room closet
SIZE:	120 G	al		_ PSI:	241	PSI	_BURIED1	? YES □	NO 🛭	
			OPERABLE 🛛							
NOTES:	Servic	<mark>e call nee</mark>	eded to service t	ne pre	<mark>essur</mark>	<mark>re tanks</mark>	and add	l air, acc	ess is difficult.	
YES 🛭		QUAN	ITITY:							
NEEDS	REPLAC	EMENT? _								
			oir on the propert t property.	y but	does	not app	pear to be	used with	n the current syster	n. There is a chance it

This Report is not to be used to determine compliance with any regulations, laws, or rules. Its sole purpose is to attempt to evaluate the operating performance of the well and pump(s) at the time of inspection. Anything can change at a moment's notice.













RECOMMENDATIONS & OR FINAL NOTES ON WELL

Summary from the well inspection:

The water well is located in the upper parking area in a vault. The well pump is located in the well with a pitless adapter. Water pumps from the well to the pressure tank which is located in the laundry room in the closet of the home. From the pressure tank the water flows through a sediment filter and then into a water softener before being distributed to the rest of the home.

The well pump control box and disconnect is located on the handrail going down the stairs from the upper parking area.

Overall, the well system is in ok condition at the time of the inspection, however we found that the control box needs to be replaced due to a leaking contactor, the wiring needs to be in conduit, a service to the water system to add air to the pressure tank, and a new sediment filter. Not servicing these items and replacing the CB can cause premature failure to the well pump.

We would recommend contacting a home plumber to look at the condition of the plumbing coming into the closet area and see if they recommend replacing that plumbing up to plumbing code.

Recommendations are:

With every water well system we recommend yearly well maintenance/service for the water system. Testing for bacteria, arsenic, nitrates, and Lead per the Arizona DOH. DOH recommends that private well owners test their drinking water every year as contaminants can change. These contaminants rapidly could affect a person's health. For more information visit the AZDOH.com

- 1. Schedule a service call to service the water system and add air to the pressure tank.
- 2. Replace the 1.5 HP Deluxe Control box.
- 3. Have the wiring placed into conduit.
- 4. Replace the current sediment filter with a new one, add salt to the tank and ResCare to the softener unit.

This Report is not to be used to determine compliance with any regulations, laws, or rules. Its sole purpose is to attempt to evaluate the operating performance of the well and pump(s) at the time of inspection. Anything can change at a moment's notice.













WATER TESTING

LAB WATER TESTING:

WATER SAMP sink.	LES TAKEN BY	ALCORN PUMP 8	SENT TO TH	LAB:	YES 🛚	№ □	Collected at kitchen		
JIIIK.				OT	OTHER:				
TAKEN TYPE:	BACTERIA ⊠	ARSENIC $oxed{\boxtimes}$	NITRATE \boxtimes	LEAD [\boxtimes				
	IPLES CAN TAKE 7		S BEFORE RECEI	VED BAC	CK FROM 1	THE LAB! ON	RD-PARTY HANDLER & NCE THE RESULTS ARE		
	FIELD	WATER TESTI	NG PERFOR	MED E	SY INSP	ECTOR:			
Raw H20 Min	eral Test	Treated H20	Mineral Test		Goo	ood Operational H20 Paramete			
PH		7.0	PH			PH 6.8-7.8			
Mang	anese	_ND	Manganese			Manganese .05			
Iron		_ND	_ Iron			Iron 0.5 ppm			
Grai	ns Hard	_1	_ Grains Hard	I		Hardness Soft – 3 Grains			
TDS		_ 69	TDS						
	FIL	TRATION NOT	ES AND REG	COMM	ENDATI	ONS:			
FILTRATION E	QUIPMENT: YE	S ⊠ NO □							
TYPE AND SIZ	E OF FILTRATIO	N? 4.5"X10" Pr	e sediment filt	er and 2	2CU Softe	ener			
NOTES ON WA	ATER AND FILTE	RATION EQUIPM	ENT: We were	not ab low on	le to test salt. We	raw water did see th	because we had no at the bypass valve		
This Report	is not to be use	ed to determine	compliance	with a	ny regul	ations, la	ws, or rules. Its sole		

Alcorn Pump & Filtration | 928-237-4372 office@alcornpump.com | www.alcornpump.com ROC# 339937

purpose is to attempt to evaluate the operating performance of the well and pump(s) at the time of inspection. Anything can change at a moment's notice.















PHOTOS OF PUMPING SYSTEM









This Report is not to be used to determine compliance with any regulations, laws, or rules. Its sole purpose is to attempt to evaluate the operating performance of the well and pump(s) at the time of inspection. Anything can change at a moment's notice.
















Plumbing to softener



This Report is not to be used to determine compliance with any regulations, laws, or rules. Its sole purpose is to attempt to evaluate the operating performance of the well and pump(s) at the time of inspection. Anything can change at a moment's notice.









